

### **EXAMPLE BLOCK**

19 Example Rd, Vredehoek, Cape Town, 0000

Date: 26 January 2024

ATTN: Example Block Trustees
To: John Doe <Johnnyd@gmail.com>
Joe Doe <Joedoe@mweb.com>
Cc: Jane Doe <Jane@property.co.za>

### **REPORT**

## **Tuesday 9 January 2024**

12h28



- Guys wiring up power for a sauna that's going to be installed. Confirmed to be Jane, permission has been given.
- Checked on lift doors, slight catching on ground floor but nothing serious.



# Wednesday 17 January 2024

13h12



- Sauna is installed.
- Electrical looks sealed.



• Security gate will not be able to open with this conduit.








Cracking evident at Example court rear outside Joe's unit





 New tiling should prevent further damp damage in future. There is considerable water damage to soffit beneath that needs to be addressed now that waterproofing is considered finalised





• Stairs in bad condition pre construction, agitated by construction activities, painting required



• Cable needing trunking/tubing, is to owners account





Pipes need painting and wall, first floor Example where the renovation was done





Bird spikes need to be installed and pipes cleaned along with the painting in the same area



# Thursday 18 January 2024

11h16




Cracking beam, first floor Example requiring attention



• Quote to replace/ repair





• Quote for full tiling of both staircases at Jocyn Court, external and internal staircases



• Buy Q20 for Caretaker to maintain metal items





Barbed wire needed for Example back passage, quote requested by Joe



• New padlock with 4 keys requested by Joe, supplied this week





Repaint back wall, rear passage



• Cracking appearing below window on same face





- Example rear, 2nd floor passage beneath newly tiled walkway showing water damage, requiring replastering and painting
- Lighting solution requested for loadshedding by Joe
- Budgetary estimates compiled for the end of next week.

## Thursday 25 January 2024

#### 11h56

Supplied hose and fittings as well as q20 for Caretaker

Kind regards, Thomas Quinn thomasworkmails@gmail.com 078 683 3972

# Example Block

0	Tar repair in parking lock  ☐ Note
	parking bay 3 has damaged tar and is requiring repair
0	garage 17 waterproofing  □ Note
	Contractor has worked but job is incomplete
0	Unit 5 conduit and pipes on common property  □ Note
	Affecting functional use of common property
0	Waterproofing to Unit 9 roof  □ Note
	Reported leaks into unit 9
0	Garage roof waterproofing
0	Spalding concrete on front passage  □ Note
	possible structural damage
0	Several lights requiring new bulbs  □ Note
	Lights in stairway are damaged from water ingress and should be replaced with IP rated lights for their exposure
Completed	
•	Tiles in back stairway  □ Note
	tiles are damaged and need replacing
•	10 year plan
•	Weeds on wall